



## NaOH (Lye) Analysis

Property	Units	Value
Purity(NaOH)	Wt%	49±1 min
Na <sub>2</sub> CO <sub>3</sub>	Wt%	0.4 max
NaCl	Wt.ppm	15 max
Na <sub>2</sub> SO <sub>4</sub>	Wt.ppm	15 max
Al <sub>2</sub> O <sub>3</sub>	Wt.ppm	10 max
Total Fe	Wt.ppm	6 max
SiO <sub>2</sub>	Wt.ppm	5 max
Total Ca	Wt.ppm	10 max
Hg	Wt.ppm	0.5 max
NaClO <sub>3</sub>	Wt.ppm	120 max